中国认可
国际互认
检测
TESTING
CNAS L3742

# TEST REPORT

Scan to see the report

XMIN2508001885CM01
Verification:
check.sgsonline.com.cn

**No. : XMIN2508001885CM01_EN**

**Date : 2025-08-22**



CUSTOMER NAME: ARLON GRAPHIC MATERIALS Co., LTD

ADDRESS: NO. 1989 XINCHANG NORTH ROAD, CHANGLE WEIFANG, SHANDONG, 262400 CHINA

Sample Name : SERIES 3515

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

**********

SGS Ref. No. : QDIN2508001588PL01

Date of Receipt : 2025-08-14

Testing Period : 2025-08-14 ~ 2025-08-22

Test result(s) : For further details, please refer to the following page(s)
(Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for
SGS-CSTC Standards Technical
Services Co.,Ltd. Xiamen Branch.

Bryan Hong
Authorized signatory

检验检测专用章
Inspection & Testing Services
SGS-CSTC Standards Technical Services Co.,Ltd. Xiamen Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5765857 www.sgsgroup.com.cn
中国·福建·厦门·火炬（翔安）产业区翔虹路31号 邮编：361101 t (86-592) 5765857 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

# TEST REPORT

**No. : XMIN2508001885CM01_EN**


**Date : 2025-08-22**



Summary of Results:

| No. | Test Item | Test Method | Result |
|---|---|---|---|
| 1 | Shod Ramp Test | DIN EN 16165:2023-02<br>Annex B | Ramp test value $\alpha_{shod}$: 11°<br>Slip Resistance Class: R10 |

Original Sample Photo:




Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5765857 www.sgsgroup.com.cn
中国·福建·厦门·火炬（翔安）产业区翔虹路31号 邮编：361101 t (86-592) 5765857 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

# TEST REPORT

**No. : XMIN2508001885CM01_EN**

**Date : 2025-08-22**



Test Item: Shod Ramp Test

Sample Description: See photo

Test Method: DIN EN 16165:2023-02 Determination of slip resistance of pedestrian surfaces - Methods of evaluation Annex B Shod ramp test

Test Condition:

Specimen: 1000mm×500mm, 1pc, cut from original sample, see photo

Test surface: see photo

Test direction: long side direction, see photo

Test Result:

| Test Item | Test Result | Slip Resistance Class |
|---|---|---|
| Shod Ramp Test | Ramp test value $\alpha_{shod}$: 11° | R10 |

**DIN EN 16165:2023-02 NB.2 Classification of the results by shod ramp test:**

| **Test Result** $\alpha_{shod}$ | **Slip Resistance Class** |
|---|---|
| 6°≤$\alpha_{shod}$≤10° | R9 |
| 10°<$\alpha_{shod}$≤19° | R10 |
| 19°<$\alpha_{shod}$≤27° | R11 |
| 27°<$\alpha_{shod}$≤35° | R12 |
| 35°<$\alpha_{shod}$ | R13 |

********End of report********

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5765857 www.sgsgroup.com.cn

中国·福建·厦门·火炬（翔安）产业区翔虹路31号 邮编：361101 t (86-592) 5765857 sgs.china@sgs.com

Member of the SGS Group (SGS SA)