



Avenue Gouverneur Cornez, 4
B-7000 MONS (Belgium)
Tel. (065)40.34.34
Fax (065)34.80.05

V.A.T. : BE 0413.106.271
RC MONS : 130.828 - Registration : 08/02/01

<http://www.bcrc.be/>

TEST REPORT : N° 2018B SEC 34390-6

Including 3 pages
Page 1/3

Mons, May 15th, 2018

REQUESTED BY : **AVERY DENNISON MATERIALS BELGIUM**
Bld J Fitzgerald Kennedy
7060 SOIGNIES
BELGIUM

REFERENCE OF THE REQUESTED : PO 358049

CONCERNED MANUFACTURER: **AVERY DENNISON ISRAEL LTD**
Kibbutz Hanita,
2288500, Israel


NUMBER OF SAMPLES AND IDENTIFICATION : **SF Clear 4 Mil i - see page 2**

PURPOSE OF THE REQUEST : **TEST ON SAFETY GLASS IN COMPLIANCE WITH THE
REQUIREMENTS OF THE STANDARD EN 12600:2003 (PENDULAR
TEST)***

SAMPLES RECEIVED ON : 26/04/2018

TESTING DATE : 08/05/2018

COMMENTS : * Test and/or sampling under accreditation

 **Notified body (Id.N°1174)**
according to Regulation (EU) No 305/2011 - Construction products

TEST ON SAFETY GLASS IN COMPLIANCE WITH
THE REQUIREMENTS OF THE STANDARD EN 12600 (2003)*

Tested side : Film

On 8 samples

Dimension : 876*1938 mm


Testing date : 08/05/2018

Temperature in the test room: 21.4°C

Test piece number	Actual thickness (mm)	Drop height (mm)	Inspection of the test piece after impact
1	3.98	190	Intact
2	3.97	190	Broken in compliance with the §4.a
3	3.98	190	Broken in compliance with the §4.a
4	3.97	190	Broken in compliance with the §4.a
5	3.99	450	Broken in compliance with the §4.a
6	3.98	450	Broken in compliance with the §4.a
7	3.97	450	Broken in compliance with the §4.a
8	3.98	450	Broken in compliance with the §4.a

Conclusion

The tests carried out on the samples considered in this report gave results **in compliance** with the requirements of the EN 12600 (pendulum test) standard for the safety **Classification 2B2**.



D. LIBERT
Head of Department
Glazing and Components - INISMa